

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**


Replacement Sheet

Figure 1



200

Figure 2A 202



212

210

206

218

216

220

214

208

205

213

200

Figure 2B






Figure 2C




Replacement Sheet

Figure 4




Replacement Sheet

Figure 5




Replacement Sheet

Figure 6A



Replacement Sheet

Figure 6B



Replacement Sheet

Figure 6C

600




Figure 7A






Figure 7B



Replacement Sheet


Replacement Sheet

Figure 8



900

900



Low Oil Pressure Switch

